




The WipeOS appliance that you have just received has been pre-configured for use with your account.

Portal (login.wipeos.com) credentials:

Client login credentials:

BEFORE YOU BEGIN:



Plug the network port labeled **WAN** into your main network.



Verify that your firewall rules are configured to allow outgoing connections from the WipeOS appliance, specifically for:

HTTPS: port 443 TCP

Open VPN: port 1194 UDP



Plug the network port labeled **LAN** into the network you want to boot into WipeOS. Then boot the appliance. Normal boot time is about 2 minutes.



Once WipeOS has booted, review the entire manual. Be sure to keep the WipeOS appliance in a secure area at all times.